

## How to: Move Next

1. Go to the Business Data menu.




2. Select the Material entity.




3. Select a Material.

The material selection can be done this way, or through Step or Resource View.




4. Select a the Move-Next button.


This option is available in any View, as long as the Material is in the Processed state.




5. Select the Move-Next option.



6. Select the Move-Next button.



7. Select the Move-Next button.



The screenshot displays the Critical Manufacturing 10.2 interface. A dialog box titled "Move Material to Next Step" is open, showing a "RESULTS" section. The results indicate that materials were successfully moved to the next step. The data changed includes the step being set to "Moulding", the secondary units being "Cookies", and the material system state being "Queued". A "Close" button is visible in the bottom right corner of the dialog box. The background shows a navigation menu on the left with categories like Administration, Business Data, Manufacturing, Maintenance, Quality, Planning and Logistics, Business Intelligence, Automation, Data Platform, and Apps. The top of the dialog box shows the breadcrumb path: AcetylsalicylicAcid-01 (Processed) / #P Acetylsalicylic Acid [A] (Acetylsalicylic Acid) / Mixing / 10 Kg.