



How to: Expand/Collapse Material

1. Go to the Business Data menu.



2. Select the Material button.



3. Select the desired Material.


Material

DEFAULT QUERY ▼


NAME	DESCRIPTION
Bolacha03	Bolacha03
Bolacha03.1	Bolacha03.1
Bolacha03.2	Bolacha03.2
Bolacha03.3	Bolacha03.3
Bolacha10	Bolacha10
Bolacha11	Bolacha11
Bolacha12	Bolacha12
Bolacha13	Bolacha13
Bolacha14	Bolacha14

Expand Material

4. Select the More button.



5. Select the Expand option if available.



6. Under the Expand Material wizard select the desired sub-material form.

Expand Material

SUB-MATERIALS FORM
SUB-MATERIALS

Bolacha13 (Queued) / Product02_PF [A] / Mixing / 1000 Kg

Select Sub-Materials Form

☒ Cookie

☐ Wafer

☐ Lot

Comments:

Cancel
Back
Next

7. Select the Next button.

Expand Material

SUB-MATERIALS FORM
SUB-MATERIALS

Bolacha13 (Queued) / Product02_PF [A] / Mixing / 1000 Kg

Select Sub-Materials Form

☐ Cookie

☐ Wafer

☒ Lot

Comments:

Cancel
Back
Next

8. Add the desired Sub-Material and corresponding quantity.

For more information, see [Expand Material - Critical Manufacturing Documentation Portal](#)

Expand Material

SUB-MATERIALS FORM — SUB-MATERIALS

Bolacha13 (Queued) / Product02_PF [A] / Mixing / 1000 Kg

SUB-MATERIALS	QUANTITY
Bolachas13-1	200 Kg
Bolachas13-2	200 Kg
Bolachas13-3	600 Kg

Sub-Material Details

* Name: Bolachas13-3

Primary Quantity: (Kg) 600

Container: Container

Position:

Apply Container To All Sub-Materials

Remaining Quantities: 0 Kg

Comments:

Cancel < Back Expand

9. Select the Expand button.

Cancel < Back Expand

10. Verify at the end the newly created Sub-Materials.

Expand Material

1 RESULTS

Bolacha13 (Queued) / Product02_PF [A] / Mixing / 1000 Kg

✓ Material Bolacha13 was expanded successfully

Entities you may want to open:

- Bolachas13-1
- Bolachas13-2
- Bolachas13-3


Collapse Material

11. Select the More button.

Change Split Hold Off-Flow Record Loss/Bonus Store Open Instance Perform Request Print View More


Material Storage Exceptions Data Collection Material Transfer Printing Documents Actions

12. Select the Collapse section.



13. Under the Collapse Material wizard select the desired Sub-Materials available to Collapse.

For more information, see [Collapse Material - Critical Manufacturing Documentation Portal](#)



14. Select the Collapse button.

